



3209 Old Jacksonville Highway
North Little Rock, AR 72117
P.O. Box 16083
Little Rock, AR 72231

(501) 945-3424
(501) 945-3544 FAX

MATERIAL SAFETY DATA SHEET

PRODUCT: QUADEX QM-1s RESTORE		Date Prepared: January 8, 1995	
HAZARDOUS INGREDIENTS/ IDENTITY INFORMATION		PHYSICAL/CHEMICAL CHARACTERISTICS	
Common Names	ACGIH TLV	Boiling Point: NA	Specific Gravity: 2.9-
Portland Cement	10 mg/M ³	Vapor Pressure: NA	Melting Point: NA
Admixtures	10 mg/M ³	Vapor Density: NA	Evaporation Rate: NA
Nepheline Syntite	10 mg/M ³	Solubility in Water: 75%	
Polypropylene	10 mg/M ³	Appearance and Odor: Grey and Odorless	
FIRE AND EXPLOSION HAZARD DATA		REACTIVITY DATA	
Flash Point: NA		Stability: Stable	
Special Fire Fighting Procedures: Non-Combustible Material		Conditions to Avoid: Although no hazardous reaction will occur; product should be kept dry.	
Extinguishing Media: NA		Hazardous Decomposition or Byproducts: None.	
Usual Fire and Explosion Hazards: None.		Hazardous Polymerization: Will not occur.	
HEALTH HAZARD DATA			
Routes of Entry:	Inhalation: Yes	Skin: Yes	Ingestion: Yes
Carcinogenicity:	NTP: No	IARC Monographs: No	OSHA Regulated: No
Signs and Symptoms of Exposure: May cause skin irritation, eye irritation and respiratory irritation.			
Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, lung, and skin conditions.			
Emergency and First Aid Procedures: Rinse eyes with clean water and wash affected skin with soap and water.			
PRECAUTIONS FOR SAFE HANDLING AND USE			
Steps to Be Taken in Case Material is Released or Spilled: Shovel into labeled waste container for reuse or disposal. Wear adequate protective clothing and equipment. Area may be washed down with water.			
Waste Disposal Method: Dispose in sanitary landfill in accordance with federal, state, and local regulations.			
Precautions to be Taken in Handling and Storing: Store in dry place and keep sealed until ready to use.			
Other Precautions: None			
CONTROL MEASURES			
Respiratory Protection: Use NIOSH/MESHA approved respirator.			
Ventilation: Local exhaust recommended if necessary. Mechanical exhaust recommended if necessary.			
Protective Gloves: Rubber		Eye Protection: Goggles	
Other Protective Clothing or Equipment: Standard work clothing and shoes.			
Work/Hygenic Practices: NA			